AMENDMENT OF SOLICITATI	ON/MODIFICATI	ON OF CONT	RACT	1. Contract I	D Code Economic Pri	Page 1 Of 1	3
2. Amendment/Modification No.	3. Effective Date	4. Requisition/Pur	chase Req	1	5. Project No. (		
03	2004MAY10	SEE SCI	HEDULE				
6. Issued By	Code W56HZV	7. Administered By		than Item 6)		Code	S1501A
TACOM WARREN BLDG 231		DCMA INDIA	NAPOLIS				
AMSTA-AQ-AHPC		EMMETT J. B		R			
SHIRLEY GHARAGOZLOO (586)574-7163		8899 E. 56T		240 5701			
WARREN, MICHIGAN 48397-5000 HTTP://CONTRACTING.TACOM.ARMY.MIL		INDIANAPOLI	5, IN 40	249-5/01			
EMAIL: GHARAGOS@TACOM.ARMY.MIL			GCD P	DAG NOVE	A DD D	TI ***00337	
8. Name And Address Of Contractor (No., Stre	et City County State and		SCD B	PAS NONE	ADP P	Т но0337	
	et, City, County, State and	i Zip Code)		9A. Amenumei	n Of Solicitation	140.	
CUMMINS INC. 500 JACKSON STREET							
M/C 80960				9B. Dated (See	Item 11)		
COLUMBUS, IN. 47201-6258				104 Modificat	ion Of Contract/	Order No	
			X	TOA. MIOUITICA	ion of contract	Order No.	
TYPE BUSINESS: Large Business Perfo	rming in H C		l L	DAAE07-96-D-	T024/0118		
	Iming in 0.5.			10B. Dated (Se	e Item 13)		
Code 15434 Facility Code	**************************************						
11. T	HIS ITEM ONLY APPLI	ES TO AMENDME	NTS OF SC	DLICITATION	S		
The above numbered solicitation is amend	led as set forth in item 14.	The hour and date s	specified fo	or receipt of Off	fers		
is extended, is not extended.				.•			
Offers must acknowledge receipt of this ame (a) By completing items 8 and 15, and return		and date specified in of the amendments: (					
offer submitted; or (c) By separate letter or	-				-		opy of the
ACKNOWLEDGMENT TO BE RECEIVED							
SPECIFIED MAY RESULT IN REJECTIO change may be made by telegram or letter, p							
opening hour and date specified.	orovided each telegram or	ietter makes referen	ce to the so	ncitation and t	ms amendment, a	ina is received p	orior to the
12. Accounting And Appropriation Data (If rec ACRN: AA NET INCREASE: \$122,767.32	quired)						
ACRN: AA NET INCREASE: \$122,767.32							
13. THIS	ITEM ONLY APPLIES T	O MODIFICATION	S OF CON	NTRACTS/ORI	DERS		
KIND MOD CODE: G	It Modifies The Contra	act/Order No. As Des	scribed In	Item 14.			
A. This Change Order is Issued Pursual				The Ch	anges Set Forth	In Item 14 Are I	Made In
The Contract/Order No. In Item 10.  B. The Above Numbered Contract/Orde		The Administrative (	hanges (su	ıch as changes i	n naving office	nnronriation de	ata etc)
Set Forth In Item 14, Pursuant To T	he Authority of FAR 43.10	03(b).				прргоргіацоп ца	
X C. This Supplemental Agreement Is Ent	tered Into Pursuant To Au	thority Of: Mutual	Agreemen	t of the Part	ties		
D. Other (Specify type of modification a	and authority)						
E. IMPORTANT: Contractor is not,	X is required to sign	this document and	return	0	copies to the Issui	ng Office.	
14. Description Of Amendment/Modification (	Organized by UCF section	headings, including	solicitation	/contract subje	ct matter where	feasible.)	
SEE SECOND PAGE FOR DESCRIPTION							
DEE DECOND PAGE FOR DESCRIPTION							
Except as provided herein, all terms and condi-	tions of the document refe	renced in item 9A or	10A, as he	retofore change	ed, remains unch	anged and in ful	ll force
and effect.							
15A. Name And Title Of Signer (Type or print)	)	16A. Name		Of Contracting	Officer (Type or	print)	
				Y.MIL (586)57	4-8056		
15B. Contractor/Offeror	15C. Date Signed	16B. United	States Of	America		16C. Date Si	gned
		Ву		/SIGNED/		2004	MAY10
(Signature of person authorized to sign)	-		ignature of	f Contracting C	Officer)	2004	A110
NSN 7540-01-152-8070		30-105-02			STANDARD FO	RM 30 (REV. 1	0-83)

#### Reference No. of Document Being Continued

PIIN/SIIN DAAE07-96-D-T024/0118

MOD/AMD 03

Page 2 of 13

Name of Offeror or Contractor: CUMMINS INC.

SECTION A - SUPPLEMENTAL INFORMATION

CONTRACT DAAE07-96-D-T024, DELIVERY ORDER 0118, MODIFICATION 03

DELIVERY ORDER FOR VTA-903T-600 ENGINE REMAN/UPGRADE

PRIOR NET VALUE OF DELIVER ORDER: \$2,628,702.26

TOTAL THIS ACTION: \$ 122,767.32

NEW DELIVERY ORDER VALUE: \$2,751,469.58

- a. This is a bilateral modification issued to expand the remanufacture/upgrade scope of work to include the use of some 500HP engine
- b. Thirteen (13) engines will be separated from CLIN 0160AA onto CLIN 0160AB to facilitate a \$9,443.64 each increase in unit price, which takes into account the cost differential of using 500HP rather than 600HP core for the engine remanufacture/upgrade and extension of the delivery schedule for this quantity to 30 April 2005. The Delivery Order total is increased by \$122,767.32 as outlined above.
- c. The work required for CLIN 0160AB is outlined in Attachment 003, 2004 VTA903-T500 to VTA903-T600 Engine Remanufacture and Conversion Scope of Work, which is added at Section J.
- d. All other terms and conditions remain unchanged.

\*\*\* END OF NARRATIVE A 004 \*\*\*

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

**Page** 3 **of** 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	SECTION B - SUPPLIES OR SERVICES AND PRICES/COSTS				
0159AA	PRODUCTION QUANTITY	1	EA	\$ 32,010.50000	\$ 32,010.50
	NOUN: 600HP CENTRY ENGINES				
	PRON: PF3MEXC659 PRON AMD: 02 ACRN: AA  AMS CD: 23106552019				
	110 02 25100552015				
	NSN: 2815-01-509-3958				
	P/N: 903-600PCXCO (Cummins)				
	Remanufactured VTA903-T600 ENGINE, DIESEL,				
	CUMMINS MODEL VTA903-T600 WITH CENTRY,				
	to be returned in a REFURBISHED metal Container				
	for use in the Precision Fires Mod Proram.				
	THIS IS A REMANUFACTURING EFFORT.				
	THE GOVERNMENT WILL BE PROVIDING THE				
	CONTRACTOR WITH CORE.				
	Work to be performed in accordance with				
	attached 2003 VTA903-T600 ENGINE REMANUFACTURE				
	SCOPE OF WORK.				
	THROTTLE POSITION SENSORS will not be provided				
	as part of these engines.				
	(End of narrative C001)				
	(2114 02 141240210 0002)				
	Packaging and Marking				
	PACKAGING/PACKING/SPECIFICATIONS:				
	AK14230929				
	UNIT PACK: 001 LEVEL PRESERVATION: Military				
	LEVEL PACKING: A				
	Engines will be packaged in refurbished				
	(PRM-1500) Containers with new Shear Mounts.				
	Contractor will work to TB-9-289 (refurbished)				
	in lieu of A-A-52462 (new). Instructions regarding				
	special marking for rebuilt engines will not apply to remanufactured engines.				
	to remanufactured engines.				
	Marking of exterior pack to be shown in accordance				
	with MIL-STD-129, Revision M.				
	(End of narrative E001)				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin				
	Inspection/Acceptance of this Delivery Order				
		<u> </u>	1		<u> </u>

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

Page 4 of 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	will be under the terms of FAR 52.246-15				
	Certificate of Conformance.				
	The place of performance and the				
	inspection/acceptance point for the finished product (Engine in Container)				
	is as follows:				
	Indiana Reserach Institute				
	4571 Long Road				
	Columbus, IN 47203				
	(End of narrative F001)				
	(Zilla of illatino root)				
	Deliveries or Performance				
	DOC SUPPL REL CD MILSTRIP ADDR SIG CD MARK FOR TP CD				
	001 W80FLR3139EF03 W8007A M 2				
	DEL REL CD				
	001 1 31-DEC-2003				
	FOB POINT: Origin				
	SHIP TO: FREIGHT ADDRESS				
	(W8007A) XR SPECIAL PROJECT OFFICE BRX ACCT				
	DEFENSE DIST CENTER RED RIVER 10TH AND K ST BLDG 499				
	TEXARKANA TX 75507-5000				
	CONTRACT/DELIVERY ORDER NUMBER				
	DAAE07-96-D-T024/0118				
	MARK FOR ATTENTION OF MARILYNN MURPHY				
	DELIVERY ACCELERATION IS ACCEPTABLE PROVIDED				
	THERE IS NO ADDITIONAL COST TO THE GOVERNMENT.				
	(End of narrative F002)				
	(Bid of harracive 1002)				
0159AB	PRODUCTION QUANTITY	10	EA	\$ 33,290.92000	\$332,909.20
UIJJAB	FRODUCTION COMMITTE	10	EA	<u> </u>	332,909.20
	NOUN: 600HP CENTRY ENGINES				
	PRON: PF3MEXC659 PRON AMD: 02 ACRN: AA				
	AMS CD: 23106552019				
	NSN: 2815-01-509-3958 P/N: 903-600PCXCO (Cummins)				
	Remanufactured VTA903-T600 ENGINE, DIESEL,				

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

**Page** 5 **of** 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	CUMMINS MODEL VTA903-T600 WITH CENTRY,				
	to be returned in a REFURBISHED metal Container				
	for use in the Precision Fires Mod Proram.				
	THIS IS A REMANUFACTURING EFFORT.				
	THE GOVERNMENT WILL BE PROVIDING THE				
	CONTRACTOR WITH CORE.				
	Work to be performed in accordance with				
	attached 2004 VTA903-T600 ENGINE REMANUFACTURE				
	SCOPE OF WORK.				
	THROTTLE POSITION SENSORS will not be provided				
	as part of these engines.				
	(= 1 5				
	(End of narrative C001)				
	Packaging and Marking PACKAGING/PACKING/SPECIFICATIONS:				
	AK14230929				
	UNIT PACK: 001				
	LEVEL PRESERVATION: Military				
	LEVEL PACKING: A				
	Engines will be packaged in refurbished				
	(PRM-1500) Containers with new Shear Mounts.				
	Contractor will work to TB-9-289 (refurbished) in lieu of A-A-52462 (new). Instructions regarding				
	special marking for rebuilt engines will not apply				
	to remanufactured engines.				
	Marking of exterior pack to be shown in accordance with MIL-STD-129, Revision M.				
	WICH MILE-SID-129, REVISION M.				
	(End of narrative E001)				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin				
	Inspection/Acceptance of this Delivery Order				
	will be under the terms of FAR 52.246-15				
	Certificate of Conformance.				
	The place of performance and the				
	inspection/acceptance point for the				
	finished product (Engine in Container)				
	is as follows:				
	Indiana Reserach Institute				
	4571 Long Road				
	Columbus, IN 47203				
	(End of narrative F001)				

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

**Page** 6 **of** 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Deliveries or Performance           DOC         SUPPL           REL CD         MILSTRIP         ADDR         SIG CD         MARK FOR         TP CD           001         W80FLR3139EF03         W8007A         M         2           DEL REL CD         QUANTITY         DEL DATE           002         10         04-DEC-2004				
	FOB POINT: Origin  SHIP TO: FREIGHT ADDRESS  (W8007A) XR SPECIAL PROJECT OFFICE BRX ACCT				
	DEFENSE DIST CENTER RED RIVER  10TH AND K ST BLDG 499  TEXARKANA TX 75507-5000				
	CONTRACT/DELIVERY ORDER NUMBER  DAAE07-96-D-T024/0118				
	MARK FOR ATTENTION OF MARILYNN MURPHY				
	DELIVERY ACCELERATION IS ACCEPTABLE PROVIDED THERE IS NO ADDITIONAL COST TO THE GOVERNMENT.				
	(End of narrative F002)				
0160AA	PRODUCTION QUANTITY	52	EA	\$ 33,290.92000	\$1,731,127.84
	NOUN: 600HP CENTRY ENGINE PRON: PF3MEXC559 PRON AMD: 04 ACRN: AA AMS CD: 23106552019				
	NSN: 2815-01-509-3958 P/N: 903-600PCXCO (Cummins)				
	Remanufactured VTA903-T600 ENGINE, DIESEL, CUMMINS MODEL VTA903-T600 WITH CENTRY, to be returned in a REFURBISHED metal Container for use in the Precision Fires Mod Proram.				
	THIS IS A REMANUFACTURING EFFORT. THE GOVERNMENT WILL BE PROVIDING THE CONTRACTOR WITH CORE.				
	Work to be performed in accordance with attached 2004 VTA903-T600 ENGINE REMANUFACTURE SCOPE OF WORK.				
	THROTTLE POSITION SENSORS will <u>not</u> be provided as part of these engines.				
	(End of narrative C001)				

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

**Page** 7 **of** 13

TEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Packaging and Marking				
	PACKAGING/PACKING/SPECIFICATIONS:				
	AK14230929				
	UNIT PACK: 001				
	LEVEL PRESERVATION: Military				
	LEVEL PACKING: A				
	Engines will be packaged in refurbished				
	(PRM-1500) Containers with new Shear Mounts.				
	Contractor will work to TB-9-289 (refurbished)				
	in lieu of A-A-52462 (new). Instructions regarding				
	special marking for rebuilt engines will not apply				
	to remanufactured engines.				
	Marking of exterior pack to be shown in accordance				
	with MIL-STD-129, Revision M.				
	(End of narrative E001)				
	Inspection and Acceptance				
	INSPECTION: Origin ACCEPTANCE: Origin				
	INSPECTION. OTIGIN ACCEPTANCE. OTIGIN				
	Inspection/Acceptance of this Delivery Order				
	will be under the terms of FAR 52.246-15 Certificate of Conformance.				
	Certificate of Conformance.				
	The place of performance and the				
	inspection/acceptance point for the				
	finished product (Engine in Container)				
	is as follows:				
	Indiana Reserach Institute				
	4571 Long Road				
	Columbus, IN 47203				
	(End of narrative F001)				
	Deliveries or Performance				
	DOC SUPPL				
	REL CD         MILSTRIP         ADDR         SIG CD         MARK FOR         TP CD           001         W80FLR3139EF01         W8007A         M         2				
	DEL REL CD QUANTITY DEL DATE				
	001 52 31-DEC-2004				
	FOB POINT: Origin				
	102 1011111 0119111				
	SHIP TO: FREIGHT ADDRESS				
	(W8007A) XR SPECIAL PROJECT OFFICE BRX ACCT				
	DEFENSE DIST CENTER RED RIVER				
	10TH AND K ST BLDG 499				
	TEXARKANA TX 75507-5000				
	1	İ	1	l	l

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

**Page** 8 **of** 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	CONTRACT/DELIVERY ORDER NUMBER DAAE07-96-D-T024/0118				
	MARK FOR ATTENTION OF MARILYNN MURPHY				
	DELIVERY ACCELERATION IS ACCEPTABLE PROVIDED THERE IS NO ADDITIONAL COST TO THE GOVERNMENT.				
	(End of narrative F002)				
0160AB	PRODUCTION QUANTITY	13	EA	\$ 42,734.56000	\$\$555,549.28
	NOUN: 600HP CENTRY ENGINE PRON: PF3MEXC559 PRON AMD: 04 ACRN: AA AMS CD: 23106552019				
	NSN: 2815-01-509-3958 P/N: 903-600PCXCO (Cummins)				
	Remanufactured VTA903-T600 ENGINE, DIESEL, CUMMINS MODEL VTA903-T600 WITH CENTRY, to be returned in a REFURBISHED metal Container for use in the Precision Fires Mod Proram.				
	THIS IS A REMANUFACTURING AND CONVERSION EFFORT. THE GOVERNMENT WILL BE PROVIDING THE CONTRACTOR WITH (500HP) CORE.				
	Work to be performed in accordance with attached 2004 VTA-T500 TO VTA903-T600 ENGINE REMANUFACTURE AND CONVERSION SCOPE OF WORK.				
	THROTTLE POSITION SENSORS will $\underline{not}$ be provided as part of these engines.				
	(End of narrative C001)				
	Packaging and Marking PACKAGING/PACKING/SPECIFICATIONS: AK14230929 UNIT PACK: 001				
	LEVEL PRESERVATION: Military LEVEL PACKING: A				
	Engines will be packaged in refurbished (PRM-1500) Containers with new Shear Mounts.				

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

**Page** 9 **of** 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Contractor will work to TB-9-289 (refurbished) in lieu of A-A-52462 (new). Instructions regarding special marking for rebuilt engines will not apply				
	to remanufactured engines.  Marking of exterior pack to be shown in accordance				
	with MIL-STD-129, Revision M.				
	(End of narrative E001)				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	Inspection/Acceptance of this Delivery Order will be under the terms of FAR 52.246-15 Certificate of Conformance.				
	The place of performance and the inspection/acceptance point for the finished product (Engine in Container) is as follows:				
	Indiana Reserach Institute 4571 Long Road Columbus, IN 47203				
	(End of narrative F001)				
	Deliveries or Performance           DOC         SUPPL           REL CD         MILSTRIP         ADDR         SIG CD         MARK FOR         TP CD           001         W80FLR3139EF01         W8007A         M         2           DEL REL CD         QUANTITY         DEL DATE           001         13         30-APR-2005				
	FOB POINT: Origin				
	SHIP TO: FREIGHT ADDRESS  (W8007A) XR SPECIAL PROJECT OFFICE BRX ACCT  DEFENSE DIST CENTER RED RIVER  10TH AND K ST BLDG 499  TEXARKANA TX 75507-5000				
	CONTRACT/DELIVERY ORDER NUMBER DAAE07-96-D-T024/0118				
	MARK FOR ATTENTION OF MARILYNN MURPHY				
	DELIVERY ACCELERATION IS ACCEPTABLE PROVIDED THERE IS NO ADDITIONAL COST TO THE GOVERNMENT.				
	(End of narrative F002)				

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

Page 10 of 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
0168AA	PRODUCTION QUANTITY	3	EA	\$ 33,290.92000	\$99,872.76
	NOUN: 600 HP ENGINE REMANUFACTURE PRON: PF3MEXD759 PRON AMD: 03 ACRN: AA AMS CD: 23106552019				
	NSN: 2815-01-509-3958 P/N: 903-600PCXCO (Cummins)				
	Remanufactured VTA903-T600 ENGINE, DIESEL, CUMMINS MODEL VTA903-T600 WITH CENTRY, to be returned in a REFURBISHED metal Container for use in the Precision Fires Mod Proram.				
	THIS IS A REMANUFACTURING EFFORT. THE GOVERNMENT INTENDS TO PROVIDE THE CONTRACTOR WITH CORE.				
	Work to be performed in accordance with attached 2004 VTA903-T600 ENGINE REMANUFACTURE SCOPE OF WORK.				
	THROTTLE POSITION SENSORS will <u>not</u> be provided as part of these engines.				
	(End of narrative C001)				
	Packaging and Marking PACKAGING/PACKING/SPECIFICATIONS: AK14230929 UNIT PACK: 001 LEVEL PRESERVATION: Military LEVEL PACKING: A				
	Inspection and Acceptance INSPECTION: Origin ACCEPTANCE: Origin				
	Inspection/Acceptance of this Delivery Order will be under the terms of FAR 52.246-15 Certificate of Conformance.				
	The place of performance and the inspection/acceptance point for the finished product (Engine in Container) is as follows:				
	Indiana Reserach Institute 4571 Long Road Columbus, IN 47203				
	(End of narrative F001)				

# Reference No. of Document Being Continued PIIN/SIIN DAAE07-96-D-T024/0118 MOD/AMD 03

Page 11 of 13

ITEM NO	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
	Deliveries or Performance				
	DOC   SUPPL				
	FOB POINT: Origin				
	SHIP TO: FREIGHT ADDRESS  (W8007A) XR SPECIAL PROJECT OFFICE BRX ACCT  DEFENSE DIST CENTER RED RIVER  10TH AND K ST BLDG 499  TEXARKANA TX 75507-5000				
	CONTRACT/DELIVERY ORDER NUMBER DAAE07-96-D-T024/0118				
	MARK FOR ATTENTION OF MARILYNN MURPHY				
	DELIVERY ACCELERATION IS ACCEPTABLE PROVIDED THERE IS NO ADDITIONAL COST TO THE GOVERNMENT.				
	(End of narrative F002)				

	CONTINULATION	A CHIPPE	I	Reference N	o. of D	ocur	nent Being Continued		Page 12 of 13
	CONTINUATION	N SHEET	PIIN	/SIIN DAAEO	7-96-D	-T02	4/0118 <b>MOD/AMD</b> 0	3	
Name	of Offeror or Contracto	or: cummins in	C.						•
SECTION	G - CONTRACT ADMINIS	TRATION DATA							
	PRON/								
LINE	AMS CD/	OBLG S					INCREASE/DECREASE		CUMULATIVE
<u>ITEM</u>	MIPR	ACRN JOB OF		PRIOR A			AMOUNT		AMOUNT
0160AA	PF3MEXC559 23106552019	AA 1 3PFM	\$ IEX	2,163,9	909.80	\$	-432,781.96	\$	1,731,127.84
0160AB	PF3MEXC559 23106552019	AA 1 3PFM	\$ IEX		0.00	\$	555,549.28	\$	555,549.28
				NET CHA	ANGE	\$	122,767.32		
SERVICE NAME Army	NET CHANGE BY ACRN AA		CLASSIFICAT		S0102	1	ACCOUNTING STATION W31G3H	\$	INCREASE/DECREASE AMOUNT 122,767.32
							NET CHAN	GE \$	122,767.32
NET CHA	NGE FOR AWARD: \$	PRIOR A OF AW 2,628,702	ARD	\$		AMOU	/DECREASE INT	CUMULAT	

Name of Offeror or Contractor: CUMMINS INC.

SECTION J - LIST OF ATTACHMENTS

List of Addenda Title Date of Pages Transmitted By

**PIIN/SIIN** DAAE07-96-D-T024/0118

Reference No. of Document Being Continued

**MOD/AMD** 03

Page 13 of 13

Attachment 003 2004 VTA903-T500 TO VTA903-T600 ENGINE REMANUFACTURE AND

ONTERSTON COORS OF MORE

CONVERSION SCOPE OF WORK

**CONTINUATION SHEET** 

 PIIN/SIIN
 DAAE07-96-D-T024/0118

 MOD/AMD
 03

 ATT/EXH ID
 Attachment 003

 PAGE
 1

#### VTA903-T500 to VTA903-T600 Engine Remanufacture and Conversion Scope of Work

This Statement of Work (SOW) will serve as the vehicle for tasking Cummins Inc. (Cummins) for the remanufacture/conversion of VTA903-T500 engines to VTA903-T600 engines for the US Army, as needed. There is no time limit for this SOW; however, the included engine pricing and replacement core charge list will be updated annually.

The VTA903-T500 core for the engines to be remanufactured will be provided by the Government, will be considered by Cummins as core material, and, therefore, will become the property of Cummins. Unusable core will require replacement either by providing a direct replacement for the unusable core (provide useable part), or by purchasing replacement core from Cummins at pricing included in the engine replacement core charge list below.

Cummins shall remanufacture the engines in accordance with their corporate remanufacturing practices and standards. Upon completion of the engine remanufacture, Cummins shall be responsible for arranging shipping of the remanufactured engine to the location/address provided. Cost of transportation can be included in the Remanufacture/Conversion engine pricing, or funded separately. Delivery of the remanufactured engine(s) shall be negotiated at the time of purchase.

Cummins shall provide the remanufactured engine with a new serial number and the same base engine warranty as provided with new production engines. Estimated completion dates can be provided upon request. The agreed upon deliverable for each acceptable VTA903-T500 core engine shall be a remanufactured engine in the most current production configuration for the VTA903-T600 engine.

Cummins can also provide refurbished PRM-1500 or 12298163 containers for engine core material provided to Cummins in used PRM-1500 or 12298163 containers. Used PRM-1500 or 12298163 containers as core for the refurbishing process provided by the Government, will be considered by Cummins as core material, and, therefore, will become the property of Cummins. Cummins will notify the Government of any unusable PRM-1500 or 12298163 container core.

The agreed upon deliverable for each acceptable PRM-1500 or 12298163 core container shall be a refurbished PRM-1500 or 12298163 container. Containers shall be refurbished in accordance with Department of the Army Technical Bulletin TB9-289, and marked in accordance with MIL-STD-129M.

**PIIN/SIIN** DAAE07-96-D-T024/0118

MOD/AMD 03
ATT/EXH ID
PAGE 2

#### Engine Remanufacturing & Option Pricing, and Replacement Core Charge List

Calendar Year 2004

VTA903-T600 Conversion Engine Remanufacture Price

\$36,400.00

Component	P/N	Core Value
Crankshaft	AR12976	\$2,522.16
Camshaft	3072869	\$ 567.28
Cylinder Head Castings	180102	\$1,037.80
Camshaft Gear	3031728	\$ 160.89
Connecting Rods	3073579	\$ 131.30
Transmission Oil Cooler	3066146	\$ 977.77
Vibration Damper	3552912	\$ 256.17
Rocker Lever Housing	3086378	\$ 147.58
Rear Crank Adapter	215633	\$ 108.84
Flywheel Housing	3017378	\$ 534.05
Flywheel	3004152	\$ 146.12
Radiator Support	3017395	\$ 94.59
Radiator Support	3017396	\$ 75.51
Gear Cover	3160999	\$ 95.21
Option Pricing	CENTRY	\$1,560.00
	Export Box	\$ 312.00
	Refurbished Container	\$3,130.92

 PIIN/SIIN
 DAAE07-96-D-T024/0118

 MOD/AMD
 03

 ATT/EXH ID
 PAGE

#### REBUILD VS REMANUFACTURE

Rebuilding of a heavy duty Cummins engine (such as the V903) typically involves the replacement of wear components such as the engine bearings, piston rings, cylinder liners, etc. An extensive rebuild can also include requalification of some of the engine critical areas such as the upper and lower counter bore areas of the cylinder block for proper fit of the replaceable wet cylinder liners. Rebuild of major components is also typically a part of an extensive engine rebuild.

Cummins' shop manuals, available for the various model engines, provide the needed information for service re-use of certain components, and instructions for disassembly and reassembly of the engine. Rebuilding is typically performed in a job shop type of environment, even when fairly large quantities are involved.

Remanufacture of an engine is essentially restoring the engine to a like new condition. The single most important ingredient that segregates a new engine from one that is remanufactured is that the new engine cannot contain any used parts, whereas the remanufactured engine can.

Remanufacturing an engine includes inspection of all areas of wear, including areas of the engine that are known to wear after extensive operation that are not classified as wear areas in terms of rebuild. These areas, which include, but are not limited to, the turbocharger turbine and compressor casings, the water pump housing, certain areas of the cylinder block, etc., usually have some degree of wear due to relative movement of component assembly members from vibration or thermal expansion and contraction, and may have some minor damage due to contact with moving components that became excessively worn during operation, or failed.

During a remanufacturing process, such as that used by Cummins, areas where wear can occur are requalified to new engine condition. This can involve the addition of material, and then machining the component to new engine manufacturing print specifications, which requires access to Cummins' proprietary drawings. The entire engine work process is conducted in a mass production environment (as opposed to the earlier job shop environment), and the end product carries a warranty that is the same or similar to the new engine warranty.

The remanufacture of Cummins V903 family of engines is conducted in the same facility as is used for the production of new engines. A remanufactured V903 engine is assembled, tested, and finish processed using the same procedures, equipment, and personnel that are involved in the manufacture of a new V903 engine.

While there are many areas of detail that differentiate an engine rebuild from an engine remanufacture, the primary ones are the environment of the work (job shop vs. production) and the end level to which the product is taken (replacement of wear items vs. return to a like new condition), and the product warranty.

 PIIN/SIIN
 DAAE07-96-D-T024/0118

 MOD/AMD
 03

 ATT/EXH ID
 4

#### CORE QUALIFICATION

CORE ACCEPTANCE IS BASED ON AN EXTERNAL AND INTERNAL INSPECTION. CORE IS ACCEPTABLE IF CORE INSPECTION INDICATES FOLLOWING:

- 1. Core is complete with applicable engine component parts per Cummins Engine Company, Inc. specifications and drawings.
- 2. Primary engine and component castings are not visibly cracked, broken, or damaged.
- 3. Core is not damaged by non-operational causes such as rust, rough handling, or fire.
- 4. Core is free from all oils and fluids except for normal drainage that occurs during shipment. An additional charge will apply if core does not meet this standard.
- 5. Core has not been subjected to any salvage techniques that would render critical areas out of dimensional tolerance or otherwise unusable.